
REPLACEMENT PARTS SUITABLE FOR

Hypertherm®

POWERMAX® 1100 PAC®135T/M



Item	Part No.	Ref. No.	Description	Std. Pkg.	Item	Part No.	Ref. No.	Description	Std. Pkg.
1.	T-2237	120475	Shield, Hand	1	*9.	T-2532*	120518-UR	Nozzle, Extended	5
2.	T-2238	120516	Shield, Machine	1	10.	T-2245	120474	Swirl Ring	2
3.	T-2239	120519	Deflector	1	11.	T-2246	120473	Electrode	5
4.	T-2240	120483 OEM	Retaining Cap	1	12.	T-2247	120517	Electrode, Extended	5
5.	T-2241	120520 OEM	Retaining Cap	1	13.,16.	T-0537	120477	PAC®135TTorch, Hand + Handle	1
6.	T-2527	T-2527	Tip Spring	1	14.	T-2842	120508	PAC®135M Torch Machine	1
7.	T-2531	120476-UR	Nozzle 80A	5	15.	N-10082	1-020S	O-Ring	1
8.	T-2530	120515-UR	Nozzle 40A	5	#16.	T-1040#	9-5636-1	Handle	5

- * FULLY INTERCHANGEABLE WITH ORIGINAL PARTS, BUT DIFFERS FROM ORIGINAL DESIGN
- # ONLY FOR THERMACUT TORCH DESIGN

Last update of this page: 17/11/2015. See Revision history for details.

THERMACUT

WWW.THERMACUT.CZ TEL.: +420,556,423,418 SALES@THERMACUT.CZ WWW.THERMACUT.DE
TEL:: +49/(0) 27 39 40 33 0
INFO@THERMACUT.DE

WWW.THERMACUT.COM
TEL.: 1/603/542-6715
CUSTOMERSERVICE@THERMACUT.COM